


TYPE S

See plans for arm length and signal spacing details



Brackets shall be located and installed in the field. Pelco AB0125-3-62 (3 section heads), Pelco AB0138-5-62 (5 section heads) or approved equal. Measurement "B" is determined by measuring from the center of the shaft to the center of the first mounting bracket. Subsequent measurements are made from center of bracket to center of bracket.

NOTES:

All steel poles require a shoe base.

See plans for base and conduit information.

Contractor will provide the Engineer with 5 (five) sets of shop drawings for approval. No poles will be set unless approved by the Engineer.

NOT TO SCALE